

CNC Router

Quick start guide



PART 1

Generating the code

This guide assumes that you have just finished modelling a part in FreeCAD's Part Design workbench, and are reading to use the CNC. Next steps:

1. Head to the  Path workbench

2. Select "Job"  from the toolbar

3. Select all relevant bodies from the dropdown and click "OK"

FreeCAD will then take you directly to the Job editor.

The default tab is the Setup tab. We will make two changes:

1) Change the Ext. Z to 0 mm

Job Edit

General Output **Setup** Tools Workplan Op Defaults

Layout

Stock


Extend Model's Bound Box Refresh

Ext. X	1.00 mm	<input checked="" type="checkbox"/>	1.00 mm	<input checked="" type="checkbox"/>
Ext. Y	1.00 mm	<input checked="" type="checkbox"/>	1.00 mm	<input checked="" type="checkbox"/>
Ext. Z	0.00	<input checked="" type="checkbox"/>	0.00	<input checked="" type="checkbox"/>

Alignment


Move to Origin Set Origin

Center in Stock XY in Stock





The default tab is the Setup tab. We will make two changes:


2) Select the corner of the stock material and select "Set Origin"



Always ensure that the coordinate axes are pointing along the edges of the stock material!




Next, go to the Output tab and select linuxcnc in the Processor dropdown:



Then click OK to exit the editor.

Now we have to specify what milling bit(s) we plan to use.

1. Open the ToolBit Dock



2a. Select a tool by clicking  **, or**

2b. Create a custom tool by clicking the  **icon**


Next we have to specify what milling bit(s) we plan to use.

1. Open the ToolBit Dock 

2a. Select a tool by clicking , or

2b. Create a custom tool by clicking the  icon

Same icon, different function




Next we have to specify what milling bit(s) we plan to use.

1. Open the ToolBit Dock



2a. Select a tool by clicking  , or

2b. Create a custom tool by clicking the  icon



Nr	Tool	
1	6mm Endmill004	en
2	5mm Drill	d
3	6mm Ball End	b
4	6 mm Bull Nose	b
5	60 Deg. V-Bit	v-
6	45 Deg. Chamfer	cl
7	Slitting Saw	sl
8	Probe	p
9	5mm-thread-cutter	th
10	Large surfacing bit	en
11	Large surfacing bit	en



Shape Attributes



Tool Bit



Name



Shape File ...


Parameter

Cutting Edge Height  

Diameter  

Length  

Shank Diameter  




Cancel OK

- **Double-click** an existing tool to edit

Use callipers to measure bits accurately


- Give your tool a useful name

3. Double-click the tool in the Tool folder of your job



4. Enter some values for
Horiz. Feed
Vert. Feed
Spindle

Note for the OMNI:
Feeds and speeds will be set manually during hardware setup, but the software still requires nonzero entries initially.




PATH GENERATION

General steps


1. Select a lines or a face

2. Select an operation



3. Choose a tool

4. Adjust the settings in the tabs




PATH GENERATION

General steps

1. Select a face

2. Select an operation



3. Choose a tool

4. Adjust the settings in the tabs



Most important

Depths

Depths

Start Depth

0.00 mm



Origin is set at the top of the material ($Z = 0$)

Final Depth

-8.00 mm



Bottom of material is below the origin ($Z < 0$)

Step Down

3.00 mm



Should be reasonable: half the bit diameter or less usually


Finish Step Down

0.00 mm










Optional thin final cut layer. Set to 0 to ignore

Operation

 Operation

Important!

Tool Controller	TC: 6mm Endmill004	
Coolant Mode	None	
Cut Mode	Climb	
Pattern	ZigZagOffset	Depends on application 
Angle	45.00 °	
Step Over Percent	80	Depends on application 
Pass Extension	0.00 mm	

Use Start Point

Use Outline

Min Travel

Recommended settings



Facing



Pockets



Profiles

Base Geometry

Depths

Heights

Operation

Tool Controller: TC: 6mm Endmill004

Coolant Mode: None

Boundary Shape: Boundbox

Cut Mode: Climb

Pattern: ZigZag

Angle: 45.00 °

Step Over Percent: 80

Material Allowance: 0.00 mm

Use Start Point

Use Outline

Clear Edges

Min Travel

Base Geometry

Extensions

Depths

Heights

Operation

Tool Controller: TC: 6mm Endmill004

Coolant Mode: None

Cut Mode: Climb

Pattern: ZigZagOffset

Angle: 45.00 °

Step Over Percent: 80

Pass Extension: 0.00 mm

Use Start Point

Use Outline

Min Travel

Base Geometry

Depths

Heights

Operation

Tool Controller: TC: 6mm Endmill004

Coolant Mode: None

Cut Side: Outside

Direction: CW

Extra Offset: 0.00 mm

Use Start Point

Use Compensation





Process Holes

Process Circles



Process Perimeter

Choose for each cut

MINIGAME: Spot the difference!



MINIGAME: Spot the difference!




The main body is hidden and **model body** is made visible


Path Dressups

Sometimes you may need to modify the paths that are generated by default:


1. Select an operation



2. Select a dressup



Path Dressups







Most common

Dogbone dress-up

Before

After







Dogbones **clear the corners** of an interior cut

Tag dress-up

Before

After



Tags **stop cut material** from moving around



CAM Simulator


Cancel

OK

Path Simulator

Speed: 50 G/sAccuracy: 0.1%Job:

- MillFace
- Pocket_Shape
- Profile



This tool shows how a simulation of how the job will go

Multi-bit jobs

Sometimes you may want to use different bits for different paths.

To do this, we can **selectively hide** certain operations and export multiple gcodes — one for each bit


This icon is used to hide/reactivate operations:



WARNING: Path dress-ups may be lost upon deactivation

Post processing

1. Select the whole job



2. Hit the post process button



3. Save the file with an explicit **.gcode** extension

Save As:

PART 2

Operating the machine

STEP 1:

Operating the machine is
a **two step** process.

OPERATION OVERVIEW

1. Preparing the bed

- Secure bit in chuck
- Place spoilboard under material
- Check material level
- Secure material along XY
- Secure material along Z

2. Running the file

- Zero the machine
- Select a file
- Adjust speeds/feeds
- Run a 'ghost pass'
- Run the file

STEP 1:

**PREPARING
THE BED**

BED PREP CHECKLIST

- Secure bit in chuck**
- Place spoilboard under material**
- Check material level**
- Secure material along XY**
- Secure material along Z**

BED PREP CHECKLIST


- Secure bit in chuck**
- Place spoilboard under material**
- Check material level**
- Secure material along XY**
- Secure material along Z**

NOTE ON BRAD NAILS/FASTENERS:


- **Double check that they are away from the machine path**
 - **Do not penetrate the base CNC bed**

STEP 2:
RUNNING A
FILE

0. Turn the machine on




1



2

0. Turn the machine on



Press **OK** to select 'All axis home'

1. Zero the machine

Use the **X+**, **X-**, **Y+**, **Y-**, **Z+**, **Z-** keys to move the milling bit around around

Use the **XY->0**, **Z->0** to set the origin coordinates



1. Zero the machine

Use the **X+**, **X-**, **Y+**, **Y-**, **Z+**, **Z-** keys to move the milling bit around

Use the **XY->0**, **Z->0** to set the origin coordinates




Recommended: set Z origin **above material to perform 'ghost pass' (see later)**

2. Select a file


Select **RUN/PAUSE** to begin loading your file



2. Select a file



Press **OK** to select 'UDisk File'



Use **arrow keys** to highlight gcode. Click **OK** to select

3. Adjust speeds/feeds




Press **DELETE** to edit an entry



Use **numpad** to type new entry


3. Adjust speeds/feeds

Entry can be edited when **only numbers** are highlighted



Use **numpad** to type new entry

3. Adjust speeds/feeds



Press **OK** to save new entry

Press **OK** again to start!

4. Ghost pass


Running files will display the following information:



4. Ghost pass

Running files will display the following information:

Coordinates of
milling bit



Spindle speed
(on scale from
1-8)

Feed rate
(translational speed
from 0.1 to 1)

4. Ghost pass

Adjust the speeds and feeds during operation with the **Y+**, **Y-**, **Z+**, **Z-** keys



Spindle speed
(on scale from
1-8)

Feed rate
(translational speed
from 0.1 to 1)

4. Ghost pass

Operation info will SAVE for the next run.

4. Ghost pass

Operation info will SAVE for the next run.

This is one of the reasons the ghost pass is recommended:

Operators can tune the speeds and feeds before actually cutting any material


5. Run the file

1. When ready, press **STOP/CANCEL** to cancel the ghost pass

2. Discard the **break** point

3. Re-zero the Z axis to the top of the material

4. Run the file (following steps from ghost pass)



Manual operation

You can also run the mill manually.

Pressing the **ON/OFF** button will stop/start the milling bit



This can be useful for manual planing or experimentation.